Audi Navigation Plus
Software Update!

The latest software available for the Nav Plus is Nov 15, 2001. If your unit does not have this update, below are the instructions to update your unit.

What the software does:

- You do not have to update the software in your Nav plus, but Audi added some new features that are kinda nice.

- Features of the latest release include:

- 50 meter range.
- The compass display.
- Some enhanced GPS coordinate displays and volume control.
- The speller function that greys out letters not possible.
- The ability to enter an intermediate destination.
- A bug fix for a volume problem with the TV tuner where it was much louder than the radio.

Creating the software disk:

- First you will need the software update. You can download it here either in Nero format, or in ISO (EZCD creator) format.

- When you unzip this 2.2MB file, you will end up with either a 135MB NRG (Nero image file), or a 128MB ISO (EZCD Creator) file. I know 2.2MB doesn't seem like it should expand to 135MB, but it does work.
- You will need either Nero or EZCD to do the update. If you have neither, you can download a trial version from Nero. Double click the image file you expanded. It's all set to burn the update disk. You will end up with a CD ROM with about 10 files on it.
- I saw some notes about what kind of CD's to use, and that "green ones" work the best. I use FujiFilm 700MB disks and have never had a problem. Note that this version of the update will only update Nav Plus D-Navi units. Don't try it in others.

Updating your Nav Plus software:

- This will take about 30 minutes.

- First you will need to eject the existing navigation disk. Press the "Mode" key. On the menu that appears, select "Settings" and press the right knob. In the menu that appears, select "Eject CD ROM" and press the right knob. The disc should eject.
- Power off the unit.

With the unit powered off, press and hold the Navigation button and the flag button. Continue to hold these as you power the unit on.

- You should end up in the software update menu. Insert the disk you created in the step above. Once it's loaded, the CD Software should show Nov 15, 2001. This should be newer than the current software, if not, you don't need the upgrade.
- Using the control knob, select "Start Control unit" and press the knob.
- The system will go through a series of displays as it loads. If the CD is ejected, simply re-insert it.

CD-ROM Software-Download

- Head Unit -

Initialization

CD-ROM Software-Download

- Head Unit -

loading data...

CD-ROM Software-Download

- Head Unit -

loading data...

- Once the above item is finished, the unit powers off. Don't panic, it should restart within

about 5 minutes. If it doesn't after 5 minutes, press the power knob and the unit will continue with the next steps.

- Once the above items are finished, you should end up back at the software menu, except now it should show the current software as Nov 15, 2001. If you have a TMC, you can use the same disk to update it.
- Eject the CD ROM using the menu item, then power the unit off. Wait 30 seconds and power the unit back on. It will ask for a CD. Insert your navagation CD and you should be good to go.

Home

Click to subscribe to AudiNav